

Errata sheet for TIA/EIA-568-B.2.

This sheet contains corrections to the document as shown.

1 PAGE: 52 CLAUSE: D.5.2

Change from: Clause D.7 specifies a systematic termination procedure that may be used to manufacture a set of plugs likely to satisfy the modular test plug requirements of clause D.6.10.

Change to: Clause D.7 specifies a systematic termination procedure that may be used to manufacture a set of plugs likely to satisfy the modular test plug requirements of clause D.5.10.

2 PAGE: 55 CLAUSE: D.5.8

Change from: Maintain correct wire pair polarity as specified in clause D.6.5.

Change to: Maintain correct wire pair polarity as specified in clause D.5.6.

3 PAGE: 58 CLAUSE: D.6

Change from: It is necessary to obtain a set of test plugs that complies with clause D.6.10.

Change to: It is necessary to obtain a set of test plugs that complies with clause D.5.10.